OMRON Temperature Meter

K3MA-L

Highly Visible LCD Display with 2-color (Red and Green) LEDs

- Wide input range select from two types of platinum-resistance thermometers and ten types of thermocouples.
- Front-panel key operation for easy setting.
- Average processing function suppresses flicker.
- Temperature input shift and temperature unit selection functions.
- Easy confirmation of max/min display.
- Short 80-mm depth (measured from edge of face plate).
- Finger protective cover (standard equipment) protects against electric shock.
- Water- and dust-proof NEMA4X (IP66 equivalent) front panel.
- Recognized to U.S. and Canadian requirements under the Component Recognition Program of UL with CE marking.

Ordering Information

Input type	Supply voltage	Output	Model
Platinum-resistance thermometer or	100 to 240 VAC	None	K3MA-L 100-240VAC
thermocouple		1 relay contact output (SPDT)	K3MA-L-C 100-240VAC
	24 VAC/VDC	None	K3MA-L 24VAC/VDC
		1 relay contact output (SPDT)	K3MA-L-C 24VAC/VDC

Model Number Legend:

K3MA-<u>L</u>- \square

1. Input Type

L: Platinum-resistance thermometer or thermocouple

2. Output Type

None: No output

C: With relay contact output (SPDT)

3. Supply Voltage

100-240VAC: 100 to 240 VAC 24VAC/VDC: 24 VAC/VDC



1

Specifications

Ratings

	K3MA-L 100-240VAC, K3MA-L-C	100-240VAC	K3MA-L 24VAC/VDC, K3MA-L-C 24VAC/VDC			
Supply voltage	100 to 240 VAC		24 VAC (50/60 Hz), 24 VDC			
Operating voltage range	85% to 110% of the rated supply vo	Itage				
Power consumption (under maximum load)	6 VA max.		4.5 VA max. (24 VAC) 4.5 W max. (24 VDC)			
Insulation resistance	20 M Ω min. (at 500 VDC) between e Insulation provided between inputs,	external terminal outputs, and pov	and case. wer supply.			
Dielectric withstand voltage	2,000 VAC for 1 min between extern Insulation provided between inputs,	nal terminal and o outputs, and pov	case. wer supply.			
Noise immunity	$\pm 1,500$ V on power supply terminals common mode. $\pm 1~\mu s,$ or 100 ns for square-wave no	in normal or bise with 1 ns.	±480 V on power supply terminals in normal mode. $\pm1,500$ V in common mode. $\pm1~\mu s,$ or 100 ns for square-wave noise with 1 ns.			
Vibration resistance	Vibration: 10 to 55 Hz, Acceleration: 5 min each in X, Y, and Z directions	50 m/s ² for 10 sweeps.				
Shock resistance	150 m/s ² (100 m/s ² for relay contact outputs) 3 times each on 3 axes, 6 directions.					
Ambient temperature	Operating: -10°C to 55°C (with n Storage: -25°C to 65°C (with n	o condensation o condensation	or icing) or icing)			
Ambient humidity	Operating: 25% to 85% (with no condensation)					
Ambient atmosphere	Must be free of corrosive gas.					
Approved safety standards	UL3121, conforms to EN61010-1 (Pollution degree 2/overvoltage category II) Conforms to VDE0106/P100 (finger protection)					
EMC	(EMI) Emission Enclosure:	EN61326+A1 CISPR 11 Grou	Industry up 1 class A: CISRP16-1/-2			
	Emission AC Mains: (EMS) Immunity ESD:	CISPR 11 Grou EN61326+A1 EN61000-4-2:	up 1 class A: CISRP16-1/-2 Industry 4-kV contact discharge 8-kV air discharge 10 V/m (amplitude medulated 80 MHz to 1 CHz)			
	Electrical East Transient Noise:	EN61000-4-3	2 kV (nower line)			
	Immunity Burst Noise: Immunity Surge:	1 kV line to line EN61000-4-5:	e (I/O signal line) 1 kV (power line) 2-kV line to ground (power line)			
	Immunity Conducted Disturbance: Immunity Voltage Dip/Interrupting:	EN61000-4-6: EN61000-4-11:	3 V (0.15 to 80 MHz) 0.5 cycle, 0, 180°, 100% (rated voltage)			
Weight	Approx. 200 g					

Input/Output Ratings

Relay Contact Output

Item	Resistive load (cos∳ = 1)	Inductive load ($\cos\phi$ = 0.4, L/R = 7 ms)			
Rated load	5 A at 250 VAC, 5 A at 30 VDC	1.5 A at 250 VAC, 1.5 A at 30 VDC			
Rated carry current	5 A max. (at COM terminal)				
Max. contact voltage	400 VAC, 150 VDC				
Max. contact current	5 A (at COM terminal)				
Max. switching capacity	2,000 VA, 192 W 375 VA, 36 W				
Min. permissible load (P level, reference value)	10 mA at 5 VDC				
Mechanical life	20,000,000 times min. (at a switching frequency of 1,200 time/min)				
Electrical life (at an ambient temperature of 20°C)	100,000 times min. (at a rated load switching frequency of 10 time/min)				

Measuring Ranges

Platinum-resistance Thermometer

Inj	put	Pt100			JPt100	
Range	°C	-200 to 850	-199.9 to 500.0	0.0 to 100.0	-199.9 to 500.0	0.0 to 100.0
	°F	-300 to 1500	-199.9 to 900.0	0.0 to 210.0	-199.9 to 900.0	0.0 to 210.0
Parameter		0	1	2	3	Ч

Thermocouple

Inpu	ıt	ŀ	۲		J		Г	E	L	l	J	Ν	R	S	В
Range	°C	-200 to 1300	-20.0 to 500.0	-100 to 850	-20.0 to 400.0	-200 to 400	-199.9 to 400.0	0 to 600	-100 to 850	-200 to 400	-199.9 to 400.0	-200 to 1300	0 to 1700	0 to 1700	100 to 1800
	°F	-300 to 2300	0.0 to 900.0	-100 to 1500	0.0 to 750	-300 to 700	-199.9 to 700.0	0 to 1100	-100 to 1500	-300 to 700	-199.9 to 700.0	-300 to 2300	0 to 3000	0 to 3000	300 to 3200
Parame	eter	5	5	٦	8	9	10	11	12	13	14	15	16	רו	18

Characteristics

essing
rement

Note:

The indication accuracy of the K thermocouple at a temperature of -200 to 1300° C is $\pm 2^{\circ}$ C ± 1 digit maximum. The indication accuracy of the T and N thermocouples at a temperature of -100° C or less is $\pm 2^{\circ}$ C ± 1 digit maximum. The indicator accuracy of the U and L thermocouples at any temperature is $\pm 2^{\circ}$ C ± 1 digit maximum.

The indication accuracy of the B thermocouple at a temperature of 400°C or less is unrestricted.

The indication accuracy of the R and S thermocouples at a temperature of 200°C or less is ±3°C ±1 digit maximum.

Nomenclature



Name		Functions			
1. Main indicator		Displays current values, parameters, and set values.			
2. Opera-	1	Lit when output 1 is ON.			
tion indi-	SV	Lit when a set value is being displayed or changed.			
Max Lit when the main indicator is showing the MAX value.					
Min Lit when the main indicator is showing the MIN value.					
3. Level indicator		Displays the current level that the K3MA-L is in. (See below for details.)			
4. MAX/MIN Key		Used to display the MAX and MIN values when a measurement value is being displayed.			
5. Level Key		Used to change the level.			
6. Mode Key		Used to allow the main indicator to indicate parameters sequentially.			
7. Shift Key		Used to enable a set value to be changed. When changing a set value, this key is used to move along the digits.			
8. Up Key		Used to change a set value. Used to set or clear a forced-zero function when a measurement value is being dis- played.			

Level indicator	Level
Ρ	Protect
Not lit	Operation
Я	Adjustment
5	Initial setting
F	Advanced-function setting

Operation

Main Functions

Input Types and Ranges

Parameter	Setting	Input type		Meaning			
īn-t	0	Platinum-resistance	Pt100	-200 to 850°C	-300 to 1500°F		
	1	thermometer	ermometer	-199.9 to 500.0°C	-1999 to 900.0°F		
	2			0.0 to 100.0°C	0.0 to 210.0°F		
	З		JPt100	-199.9 to 500.0°C	-199.9 to 900.0°F		
	Ч			0.0 to 100.0°C	0.0 to 210.0°F		
	5	Thermocouple	К	-200 to 1300°C	-300 to 2300°F		
	5			-20.0 to 500.0°C	0.0 to 900.0°F		
	7		J T	-100 to 850°C	-100 to 1500°F		
	8			-20.0 to 400.0°C	0.0 to 750.0°F		
	9			-200 to 400°C	-300 to 700°F		
	10			-199.9 to 400.0°C	-199.9 to 700.0°F		
	11		E	0 to 600°C	0 to 1100°F		
	12			L	L	-100 to 850°C	-100 to 1500°F
	13		U	-200 to 400°C	-300 to 700°F		
	14			-199.9 to 400.0°C	-199.9 to 700.0°F		
	15		-	N	-200 to 1300°C	-300 to 2300°F	
	15				R	0 to 1700°C	0 to 3000°F
	17			S	0 to 1700°C	0 to 3000°F	
	18		В	100 to 1800°C	300 to 3200°F		

Note: The initial value is "5" thermocouple K (-200 to 1300°C/-300 to 2300°F)."

Temperature Unit Selection

Either centigrade (°C) or fahrenheit (°F) can be selected as the temperature unit.

Parameter	Setting	Meaning
d-U	E	Display in °C.
	F	Display in °F.

OUT Types (Comparative Output Models Only)

 \mbox{OUT} 1 can be set to operate in one of the three following modes in accordance with the compared values:

Upper limit (High Acting):
The output is turned ON when the measurement

The output is turned ON when the measurement value is greater than its set value.

• Lower limit (Low Acting):

The output is turned ON when the measurement value is less than its set value.

Upper Limit (High Acting)







• Upper and lower limits (Outside Band Acting):

An upper limit (H set value) and lower limit (L set value) can be set independently.

The output is turned ON when the measurement value is greater than the upper-limit set value or less than the lower-limit set value.

Parameter	Setting	Meaning
5UE I.E	H_	Upper limit: Alarm operates at upper limit.
	Lā	Lower limit: Alarm operates at lower limit.
	Hī-Lō	Upper and lower limits: Alarm oper- ates at upper and lower limits.

Upper and Lower Limits (Outside Band Acting)



Temperature Input Shift

Input shift equivalent to the setting value supported for all points within the sensor measurement range.

Parameter	Setting
in5	- 1999 to 9999
^	



Parameter Initialization

This function returns all of the parameters to their initial values.

Parameter	Setting	Meaning
init	ōFF	
	ōn	Initializes all param- eters.

Use this to reset the K3MA-L after returning it to its factory-set condition.

Average Processing

Average processing stabilizes displayed values to minimize flicker by averaging the fluctuating input signals. Average processing can be performed for the measurement values in either of four steps (OFF, 2 times, 4 times, or 8 times).



This is useful for ignoring rapid fluctuations, e.g., eliminating spike noise.

Hysteresis (Comparative Output Models Only)

The hysteresis of comparative outputs can be set to prevent chattering in the output when the measurement value fluctuates finely near the OUT value.

Upper limit (high acting)



Changing the Display Color

The color of the value displayed can be set to either red or green. For comparative output models, the display color can be set to change from green to red, or from red to green, according to the status of the comparison criterion.



Display Auto-return Time

This function automatically returns the display to the operation level's current value if no keys are pressed for a preset time (called the display auto-return time).

Move-to-Protect-Level Time

The time required to shift to the protect level can be set as desired.

MAX/MIN Display

The maximum and minimum measurement (display) values from the time the power is turned ON until the current time can be stored and displayed. This is useful, for example, when measuring the maximum value.



External Connections

Terminal Arrangement





input

For platinumresistance thermometer input

Terminal No.	Name	Description		
(A1) - (A2)	Operation power	Connects the operation power supply.		
E4 - E6 - E5	Thermocouple or platinum-resistance ther- mometer input	Connects the thermocouple or platinum-re- sistance thermometer input.		
(E1), (E2) · (E3)	Outputs	Outputs the relay outputs.		

Block Diagram



Note: Relay output models only.

Levels

"Level" refers to a grouping of parameters. The following table lists the operations that are possible in each of the levels, and the diagram tells how to move between levels. There are some parameters that are not displayed for certain models.

Level name	Function	Measurement
Protect	Setting lockouts.	Continue
Operation	Displaying current values, and setting OUT 1 value.	Continue
Adjustment	Setting communications writing control.	Continue
Initial setting	Making initial settings of input type, output operating action, and other parameters.	Stopped
Advanced-function setting	Setting average processing, display color settings, and other ad- vanced function parameters.	Stopped



Note: The move-to-protect-level time can be set in the advanced-function setting level.

Parameters

Note: 1. Some parameters are not displayed for certain models.

- 2. The K3MA-L will stop measurement if the level is changed to the initial setting level or the advanced-function setting level.
- 3. If the input range is changed, some parameters are set to default values. Therefore, set the input range first.
- 4. Settings displayed in reversed colors are initial settings.





Settings displayed in reversed colors are initial settings.

OMRON

Press C Level Key + S Mode Key for more than 1 s.



Operation/Adjustment Lockouts

Restricts key operations for operation level and adjustment level.

Param-	Setting	Operatio	Moving to		
eter		Process value display	Set value display	adjustment level	
ōRPE	0	Allowed	Allowed	Allowed	
	1	Allowed	Allowed	Prohibited	
	2	Allowed	Prohibited	Prohibited	

• Initial setting is 0.

 This cannot be displayed on models not equipped with the comparative output function.

Setting Level Lockouts

Restricts shifting to initial setting level or advanced-function setting level.

Parameter	Setting	Shift to initial setting level	Shift to advanced- function setting level
CCPE	0	Allowed	Allowed
	1	Allowed	Prohibited
	2	Prohibited	Prohibited

Setting Change Lockout

Restricts setting changes by key operation. When this lockout is set, it is no longer possible to shift to a setting change mode.

Parameter	Setting	Setting change by key operation
YEPE	ōFF	Allowed
	ōn	Prohibited

However, all protect level parameters can still be changed.

Initial Settings





Setting Example

Initial Settings

The settings for the following example are shown here.

Example: Monitoring the temperature of an industrial furnace



Application Examples

Monitoring the temperature of an industrial furnace



- Monitoring the temperature of an industrial furnace/sintering furnace.
- Monitoring/alarm function for disinfecting equipment.

Sending a temperature alarm for molding equipment



- Monitoring (failsafe checking) abnormal temperatures in molding equipment.
- Monitoring the liquid temperature for cleaning devices.

Here, the temperature inside the furnace is to be displayed in centigrade (°C).

Temperature sensor: E52-PR Thermocouple, Measurement range: 0 to 1,400°C.

- 1. Set the K3MA-L input type to the thermocouple R input range.
 - Parameter: in-t (input type), Setting value: 15
- 2. Select centigrade (°C) as the temperature unit. Parameter: d-u (temperature unit), Setting value: L

If you are using a comparative output model, make the setting as desired.

Monitoring the bearing temperature for a generator motor



- Monitoring temperature rises in electric power generating facilities.
- Inspecting temperatures in machines and devices.

Dimensions



Optional Parts (Order Separately)

Name	Shape	Model
Splash-proof Soft Cover		K32-49SC
Hard Cover		K32-49HC

Installation

- 1. Insert the K3MA-L into the panel cut-out hole.
- 2. For a waterproof installation, insert the rubber gasket onto the body of the K3MA-L.



3. Fit the adaptor into the grooves on the left and right sides of the rear case, then push it until it contacts the panel to secure the K3MA-L.



Wiring Precautions

- Use crimp terminals.
- Tighten the terminal screws to a torque of approximately 0.5 $N{\cdot}m{\cdot}$
- To avoid the influence of noise, route signal lines and power lines separately.

Wiring

• Use the following M3 crimp terminals.



Unit Markings (Provided)

• The unit markings are not attached to the K3MA-L. Select the desired markings from the provided sheet.

V	A	X	A	%	J	Pa	Ω
s	/	N	m	W	°C	m³	k
۴	g	m	nin	m	m	rp	m
V	A	m	١V	m	ıΑ	ŀ	łz
m	n/m	nin	n OMRON				
ου	т	DUT					

Note: For scales and gauges, use the unit markings that are specified by the relevant laws or regulations.

Precautions

-/!\ Caution ·

Do not touch the terminals while the power is being supplied. Doing so may result in electric shock.

-<u>/!</u>Caution

Do not disassemble the product or touch the internal components of the product while the power is being supplied. Doing so may result in electric shock.

-/!\ Caution

Do not allow pieces of metal or wire clippings to enter the product. Doing so may result in electric shock, fire, or malfunction.

- 🕂 Caution

Perform correct settings for the product according to the control application. Failure to do so may cause unexpected operation, resulting in damage to the product or injury.

— 🕂 Caution

Take safety measures, such as installing a separate monitoring system, to ensure safety even if the product fails. Product failure may prevent comparative outputs from being generated, resulting in serious accidents.

Observe the following precautions to ensure safety.

- 1. Maintain the power supply voltage within the range specified in the specifications.
- 2. Maintain the load within the ratings specified in the specifications.
- Check each terminal for correct number and polarity before connecting it. Incorrect or reverse connections may damage or burn out internal components in the product.
- Tighten the terminal screws securely. The recommended tightening torque is 0.43 to 0.58 N·m. Loose screws may cause fire or malfunction.
- 5. Do not connect anything to unused terminals.
- Provide a switch or circuit breaker so that operators can easily turn OFF the power supply when necessary. Also provide appropriate indications of such devices.
- 7. Do not attempt to disassemble, repair, or modify the product.
- 8. Do not use the product where flammable or combustible gases are present.

Application

General Precautions

- 1. Do not use the product in the following locations:
 - Locations subject to direct radiant heat from heating equipment.
 - Locations subject to exposure to water, oil, or chemicals.
 - · Locations subject to direct sunlight.
 - Locations subject to dust or corrosive gases (particularly, sulfuric gas or ammonia gas).
 - · Locations subject to severe changes in temperature.
 - Locations subject to icing or condensation.
 - · Locations subject to shock or vibration.
- 2. Do not block heat dissipation around the product, i.e., provide sufficient space for heat dissipation.
- 3. Ensure that the rated voltage is reached within two seconds after the power is turned ON.
- 4. Conduct aging for 15 minutes min. after power is turned ON for correct measurement.

- 5. Do not touch the slit sections or terminals while the power is being supplied to prevent the product from being affected by static electricity.
- Do not lay heavy objects on the product during use or storage. Doing so may deform or deteriorate the product.
- 7. Do not use paint thinner for cleaning. Use commercially available alcohol.

Mounting

- Mount the product to a panel that is 1 to 8 mm thick.
- Install the product in a horizontal position.
- · Use crimp terminals that match screw sizes.

Noise Prevention

- Install the product as far as possible from devices that generate strong, high-frequency fields (such as high-frequency welders or sewing machines) or surges.
- Install surge absorbers or noise filters on nearby devices that generate noise (particularly motors, transformers, solenoids, magnet coils, and other devices that have a high inductance component). Do not connect a surge absorber to the temperature sensor input section of the K3MA-L.



 To prevent inductive noise, separate the terminal block wiring for the product from high-voltage or high-current power lines. Do not route the wiring for the product in parallel with or tie it in a bundle with power lines.

Take the following countermeasures against inductive noise in input lines.

Temperature Inputs

Separate the lead wire that connects the product with a temperature sensor from the load line to prevent the product from being affected by inductive noise.

- When using a noise filter for the power supply, check for the voltage and current and install it as close as possible to the Temperature Meter.
- Do not install the product near radios, television sets, or wireless devices. Doing so may cause reception interference.

Increasing Service Life

- Do not use the product in locations where the temperature or humidity exceeds the ratings or where condensation may occur. When installing the product in a panel, be sure that the temperature around the product (not the temperature around the panel) does not exceed the ratings. The product service life depends on the ambient temperature. The higher the ambient temperature, the shorter the service life. To extend the product service life, lower the temperature inside the Temperature Meter.
- Use and store the product within the temperature and humidity ranges given in the specifications. When gang-mounting Temperature Meters or arranging them vertically, heat generated by the Temperature Meters will cause the internal temperature to rise, reducing the service life. In such cases, consider forced cooling methods, such as using a fan to circulate air around the Temperature Meters. Do not, however, allow only the terminals to be cooled. Doing so will increase measurement error.
- The life of the output relays are greatly affected by the switching capacity and switching conditions. Use these relays within their rated load and electrical life. The contacts may fuse or burn if they are used past their electrical life.

Troubleshooting

When an error occurs, error details will be displayed on the main indicator. Confirm the error from the main indicator and take the appropriate countermeasures.

Level display	Main indicator	Error contents	Countermeasures
Not lit	EIII	RAM memory error	Repair is necessary.
			Consult your OMRON sales representative.
5	EIII	EEPROM memory error	When this error is displayed, press the Level Key for 3 sec- onds, and the settings will be re- stored to the factory settings.
			If the error cannot be recovered, repair is necessary.
			Consult your OMRON sales representative.
Not lit	Flashes 5.Err	Input error	Confirm that the temperature sensor is correctly connected, and that there are no broken sig- nal lines to the temperature sen- sor.
			If the condition does not return to normal, repair is necessary.
			Consult your OMRON sales representative.
Not lit	Flashes 9999	The measurement value after temperature input correction ex-	The temperature input correction value may be inappropriate.
		ceeds 9999.	Use the adjustment level to re- view the temperature input cor- rection value.
Not lit	Flashes - 1999	The measurement value after temperature input correction is	The temperature input correction value may be inappropriate.
		lower than -1999.	Use the adjustment level to re- view the temperature input cor- rection value.

ALL DIMENSIONS SHOWN ARE IN MILLIMETERS.

To convert millimeters into inches, multiply by 0.03937. To convert grams into ounces, multiply by 0.03527.

Cat. No. N109-E1-01 In the interest of product improvement, specifications are subject to change without notice.

OMRON Corporation

Industrial Automation Company

Measuring and Supervisory Controls Department Shiokoji Horikawa, Shimogyo-ku Kyoto, 600-8530 Japan Tel: (81)75-344-7108/Fax: (81)75-344-7189

Printed in Japan 1001-1M (1001) (B)