A „Time Chart Monitoring” használata






Time Chart Monitor Configuration
Trigger
Sampling
Word Addresses
Bit Addresses
Address
Symbol
D100
New...
Delete
„Jobb Klikk”
Select Trace Size
Single Word
Double Word
OK
Cancel
Upload
Help


Time Chart Monitor Configuration
Trigger
Sampling
Word Addresses
Bit Addresses
Address
Symbol
CF102
P_1s
New...
Delete
„Jobb Klikk”
OK
Cancel
Upload
Help


PLC Time Chart Monitor - NewPLC1
File
Operation
View
Options
Help
Mode
Configure...
Execute
Stop
Trigger
Read


PLC Time Chart Monitor - NewPLC1 - Data Trace1 (Time Chart Monitor)
File Operation View Options Window Help
Data Trace1 (Time Chart Monitor)
D100
0xFFFF
0x0FFF
0x0000
43.0 43.5 44.0 44.5 45.0 45.5 46.0 46.5 47.0 47.5 48.0 48.5 49.0 49.5 50
Seconds
CF102
0
43.0 43.5 44.0 44.5 45.0 45.5 46.0 46.5 47.0 47.5 48.0 48.5 49.0 49.5 50
Seconds